

APPROVED BY THE TEXAS REAL ESTATE COMMISSION (TREC)

EQUAL HOUSING OPPORTUNITY

SELLER'S DISCLOSURE NOTICE

CONCERNING PROPERTY AT: 6900 E Riverside Dr Unit 9, Austin, Texas 78741

THIS NOTICE IS A DISCLOSURE OF SELLER'S KNOWLEDGE OF THE CONDITION OF THE PROPERTY AS OF THE DATE SIGNED BY SELLER AND IS NOT A SUBSTITUTE FOR ANY INSPECTIONS OR WARRANTIES THE PURCHASER MAY WISH TO OBTAIN. IT IS NOT A WARRANTY OF ANY KIND BY SELLER OR SELLER'S AGENTS.

Seller □ is ☒ is not occupying the Property. If unoccupied, how long since Seller has occupied the Property? June 23, 2023 1. The Property has the items checked below [Write Yes (Y), No (N), or Unknown (U)]: Y Oven Y Microwave Y Range Y Dishwasher N_ Trash Compactor Y Disposal Y Rain Gutters Y Washer/Dryer Hookups Y Window Screens N Security System N Intercom System N Fire Detection Equipment Y Smoke Detector N Smoke Detector - Hearing Impaired Y Carbon Monoxide Alarm N Emergency Escape Ladder(s) N Cable TV Wiring N Satellite Dish N_ TV Antenna Y Ceiling Fan(s) U Attic Fan(s) Y Exhaust Fan(s) Y Central Heating Y Central A/C N Wall/Window Air Conditioning N Septic System Y Public Sewer System Y Plumbing System Y Fences Y Patio/Decking N Outdoor Grill <u>N</u> Spa N Pool N Sauna N Hot Tub N Pool Heater N Pool Equipment Y Automatic Lawn Sprinkler System N Fireplaces & Chimney (Mock) Y Fireplace(s) & Chimney (Wood burning) N Natural Gas Lines N Gas Fixtures N LP on Property N LP Community (Captive) N_ Liquid Propane Gas Garage: N Attached N_ Carport N Not Attached Garage Door Opener(s): N Electronic N_ Control(s) Water Heater: N Gas Y Electric N__ Well N Co-op Water Supply: Y City N MUD Roof Type: Composite (Shingles) Age: 14(approx.)

Are you (Seller) aware of any of the above items that are not in working condition, that have known defects, or that are

in need of repair? ⊠ Yes □ No □ Unknown. If yes, then describe. (Attach additional sheets if necessary):

Doors – The downstairs door was impacted by poor weather barrier and flashing installation causing water damage to the all-wood doors and all-wood door jams (2016-2017). I replaced all doors to fiberglass door with fiberglass door jams (2017) and the Association recently (May-July 2023) replaced and integrated all new weather barrier and flashings to prevent water/leaks impacting the door. No water damage or issue with the doors have been witnessed since these repairs.

Windows – The windows are double-hung windows and swell with heat and cold and sometimes require manual readjustment after opening the window, when re-closing and locking the window.

Roof – The roof has had two leaks due to poor flashing installation (first leak, 2014) and a nail coming up (second leak, 2023). The roof is scheduled for cricket and new flashing installation with special assessment funds in the near future (see attached schedule). The roof is currently in functional working order and no new leaks have occurred since the last repair.

Sidewalks – The community as a whole has some areas where the sidewalk has shifted or broken away in the common areas from weather and improper grading in places. Additionally, a small patch of sidewalk has deteriorated

at the front of the property limited common area to the right of the front door.

Walls/Fences – The community perimeter fence has damaged or missing posts in some areas along the fenceline.

4. Are y awar	ou (Seller) aware of any of the following conditions? We.	Vrite Yes	(Y) if you are aware,	write No (N) if you are	e not
N	Active Termites (includes wood destroying insects)	Υ	Previous Structura	l or Roof Repair	

N Active Termites (includes wood destroying insects)	Y Previous Structural or Roof Re
N_ Termite or Wood Rot Damage Needing Repair	N Hazardous or Toxic Waste
Y Previous Termite Damage	N Asbestos Components
Y Previous Termite Treatment	N Urea-formaldehyde Insulation
Y Improper Drainage	N Radon Gas

Y Water Damage Not Due to a Flood Event N Lead Based Paint
N Landfill, Settling, Soil Movement, Fault Lines N Aluminum Wiring

N Single Blockable Main Drain in Pool/Hot Tub/Spa* N Previous Fires

N Unplatted Easements
N Subsurface Structure or Pits

N Previous Use of Premises for Manufacture of Methamphetamine

If the answer to any of the above is yes, explain (attach additional sheets if necessary):

Previous Termite Damage – Termites were discovered in the lower back door and jam in 2017. The community was treated for termites and all doors and door jams were replaced with fiberglass doors that same year. Another unit discovered termites near the property (no damage) in 2022. Those termites were erradicated with treatment. The community is now currently on a termite treatment schedule.

Previous Termite Treatment – See explanation above. The last termite treatment was completed in 2022, next due in 2026.

Improper Drainage – The community currently has improper drainage in some of the common areas, affecting the sidewalks and parking lot areas of the community. These areas become more filled with water and the level or condition of the sidewalk can be impacted. In the past, the property had improper drainage around the front of the building and this was amended by adding rock landscaping around the front of the building and some areas of the community had drains installed.

Water Damage Not Due to a Flood Event – Water damage occurred at the downstairs backdoor (2016-2018) and the downstairs dining room ceiling (2023) from improper balcony flashing installations. The Association recently (May-July 2023) had the balcony replaced, all new flashings and weather barrier tie-ins installed, and any exterior water damage corrected. No water damage has been witnessed since these repairs have been made. Water damage in the master bedroom due to the air conditioner leaking due to condensation and a bent pan/clogged line. A/C mechanic came and cleared the line, straightened the pan and cleaned the A/C. No leaking issues since.

Previous Structural or Roof Repair – Two roof leaks caused by poor flashing installation (first one, 2014) and a nail coming up (second one, 2023). Association made repairs to the roof and replaced the flashing in 2014, and made repairs to the decking and shingles in 2023. Both leaks were in the North facing guest bedroom. No leaks or damage has been witnessed since these repairs.

* A single blockable main drain may cause a suction entrapment hazard for an individual.

						r on the Property			air?	⊠ Ye	es (if you
are aware)	lo (if you're	not awar	e) If yes,	explain.	(Attacr	additional sheets	s if necessa	ıry):			

Please see the Association special assessment schedule for upcoming, necessary roof, paint, & sealant repairs.

6. Are you (Seller) aware of any of the following conditions?* Write Yes (Y) if you are aware, write No (N) if you are not aware.

Prepared with Sellers Shield

Are you (Seller) aware of any of the	he following? Write Ye	s (Y) if you are aware, write No (N) if you are not aware.						
Room additions, structural N compliance with building of		r alterations or repairs made witho	ut necessary permits or not in						
Y Homeowners' Association	or maintenance fees	or assessments.							
Any "common area" (facili N interest with others.	ties such as pools, ten	nis courts, walkways, or other area	as) co-owned in undivided						
Any notices of violations o N Property.	f deed restrictions or g	povernmental ordinances affecting	the condition or use of the						
N Any lawsuits directly or inc	directly affecting the Pr	operty.							
N Any condition on the Prop	erty which materially a	ffects the physical health or safety	of an individual.						
Any rainwater harvesting s N water supply as an auxilia		property that is larger than 500 gal	lons and that uses a public						
N Any portion of the property	N Any portion of the property that is located in a groundwater conservation district or a subsidence district.								
if the answer to any of the above is yes, explain. (Attach additional sheets if necessary):									
Homeowners' Association or month. See attached special ass		assessments – Homeowners Ass	ociation dues of \$300.00						
If the property is located in a coas mean high tide bordering the Gulf	of Mexico, the proper	ty may be subject to the Open Bea	iches Act or the Dune						
Protection Act (Chapter 61 or 63, dune protection permit maybe recauthority over construction adjace. This property may be located near use zones or other operations. Intrecent Air Installation Compatible.	quired for repairs or impent to public beaches for a military installation formation relating to hiuse Zone Study or Jo	provements. Contact the local governments or more information. and may be affected by high noise gh noise and compatible use zone int Land Use Study prepared for a	ernment with ordinance e or air installation compatible s is available in the most military installation and may						
Protection Act (Chapter 61 or 63, dune protection permit maybe recauthority over construction adjace. This property may be located near use zones or other operations. Intrecent Air Installation Compatible.	quired for repairs or impent to public beaches for a military installation formation relating to hiuse Zone Study or Jo	provements. Contact the local governments or more information. and may be affected by high noise gh noise and compatible use zone	ernment with ordinance e or air installation compatible s is available in the most military installation and may						
Protection Act (Chapter 61 or 63, dune protection permit maybe recauthority over construction adjace. This property may be located near use zones or other operations. Intrecent Air Installation Compatible be accessed on the Internet webs military installation is located.	quired for repairs or impent to public beaches for a military installation formation relating to hit Use Zone Study or Josite of the military insta	provements. Contact the local governments or more information. and may be affected by high noise gh noise and compatible use zone int Land Use Study prepared for a llation and of the county and any necessity.	ernment with ordinance e or air installation compatible s is available in the most military installation and may						
Protection Act (Chapter 61 or 63, dune protection permit maybe recauthority over construction adjace. This property may be located near use zones or other operations. In recent Air Installation Compatible be accessed on the Internet webs	quired for repairs or impent to public beaches for a military installation formation relating to hiuse Zone Study or Jo	provements. Contact the local governments or more information. and may be affected by high noise gh noise and compatible use zone int Land Use Study prepared for a llation and of the county and any necessity.	ernment with ordinance e or air installation compatible s is available in the most military installation and may						
Protection Act (Chapter 61 or 63, dune protection permit maybe recauthority over construction adjace. This property may be located near use zones or other operations. Intrecent Air Installation Compatible be accessed on the Internet webs military installation is located.	quired for repairs or impent to public beaches for a military installation formation relating to hit Use Zone Study or Josite of the military insta	provements. Contact the local governments or more information. and may be affected by high noise gh noise and compatible use zone int Land Use Study prepared for a illation and of the county and any notes. 3 Signature of Seller	ernment with ordinance e or air installation compatible s is available in the most military installation and may nunicipality in which the						
Protection Act (Chapter 61 or 63, dune protection permit maybe recauthority over construction adjaced. This property may be located near use zones or other operations. Intrecent Air Installation Compatible be accessed on the Internet webs military installation is located. aura Ann Soran ature of Seller	quired for repairs or impent to public beaches for a military installation formation relating to hit Use Zone Study or Josite of the military insta	provements. Contact the local governments or more information. and may be affected by high noise gh noise and compatible use zone int Land Use Study prepared for a illation and of the county and any notes. 3 Signature of Seller	ernment with ordinance e or air installation compatible s is available in the most military installation and may nunicipality in which the						

